

## **Castaway Island, Fiji**

### **Notice of Rectification Works**

**6<sup>th</sup> May 2022**

Dear Partner,

Please be advised that Castaway Island, Fiji will shortly undergo Bure rectification works on the island, this will involve the removal and reinstallation of the rooves and whilst the impact to guests will be minimal, it is our duty of care to inform you of the scheduled and necessary works.

There will be residual noise from this work, however as referenced we do have noise buffer bures blocked.

Please note that the buffer bures will undergo preventative maintenance and deep cleaning during the OUT OF ORDER period.


We do apologise for the inconvenience and thank you for your understanding.

Please do not hesitate to reach out should you have any questions.

Ben Johnson

Area Director of Sales and Marketing, Fiji Islands

Mobile: +61 419 222 57



## SCHEDULE OF WORKS

### **2nd June -- 13th June 2022;**

3 bures will be OUT OF ORDER to complete the rectification works

10 buffer bures surrounding the above bures will be blocked off to minimize guest inconvenience and buffer any residual noise.

### **29th July -- 3rd September 2022;**

4 bures every 14 days will be OUT OF ORDER to complete the rectification works (Total 12 bures)

12 buffer bures surrounding the above bures will be blocked off

### **4th September --10 September 2022;**

4 bures will undergo retrofit works and 8 buffer bures surrounding the above bures will be blocked off

### **11th September -- 22nd September 2022;**

3 bures will undergo retrofit works and 12 buffer bures surrounding the above bures will be blocked off

### **31st October -- 11 November 2022;**

4 bures will undergo retrofit works and 15 buffer bures surrounding the above bures will be blocked off

### **12<sup>th</sup> November -- 23 November 2022;**

1 bure will undergo retrofit works and 9 buffer bures surrounding the above bures will be blocked off

### **16th January 2023 -- 01 February 2023**

18 bures every 4-8 days will undergo retrofit works and 10 buffer bures surrounding the above bures will be blocked off